



# 2648 Street View



#2649 Air Cond. Needs Cleaning



#2650 No Guard Rail Noted




#2651 Dry Tac Strip



#2652 Sump Basket



#2653 Corrosion Floor Drain



#2654 Stains At Framing



#2655 Older water Heater



#2656 Clean Furnace Filter Monthly



#2657 Furnace



#2658 Interior Breaker Box




#2659 Stair Stepping Noted Rear Wall




#2660 Unsecured Conduit



#2661 No Shut Off Valves



#2662 No Guard Rail



#2663 Switch To Close To Shower



#2664 Smoke Detector Above Fan



#2665 Loose Outlet Deck



#2666 Attic



#2667 Attic




#2668 Attic



#2669 View Of Roof



#2670 Gutters



#2671 Gap At Siding Around Window